CE BAUMGARTNER, ET AL RD-27,719-6 DAVID C. GOLDMAN (518) 387-5927





Fig. 1

line 3





△ Parylene on Csl but not in photodiode panel

epoxy bond area


CE BAUMGARTNER, ET AL RD-27,719-6 DAVID C. GOLDMAN (518) 387-5927


2/11







4/11














CE BAUMGARTNER, ET AL RD-27,719-6 DAVID C. GOLDMAN (518) 387-5927

8/11





10/11



11/11

